Effects of the Great East Japan Earthquake Aftershocks (7th Report)

SANYO CHEMICAL INDUSTRIES, LTD. (Japan securities code: 4471)

SANYO CHEMICAL INDUSTRIES, LTD. has fully resumed operations at the Kashima Factory (Kamisu city, Ibaraki prefecture, Japan). This follows the replacement of the short-circuited transformer which had caused loss of electrical power in parts of the factory and disruption to some of the production lines due to the aftershocks that occurred on April 11 and April 12, 2011.

We will continue to make a concerted effort to secure our product supply system for our customers.